


This has always
been there from
The beginning of time
or since 'Budha was a baby'.
(< 1990)


It can be moved. It has
Nothing to do with the Rx.
Maybe it is the mirror
Motor control or
focus control
(stepper motors).

We can clean this when the
Dewar is pulled off I
Imagine.



Old Cold load.
Defunct. But the
Octagon software
Needs it to operate
I think. → Space will
be freed up once
The new Rx come out.

You can try disconnecting
the DB-9 connector and
See if the octagon
Handheld boots up/freezes.



PXI
here?

PXI
here?

Both are control boxes used by the Octagon software. Will be removed once the dewars are replaced. I think the Octagon software expect them. e.g. freezes w/o these boxes.

This shows one of the problems of having two completely different Systems (Octagon vs PXI and Gunn vs Synthesized LO). Better to swap everything out at once if at all possible.

So yes, once again the Lhe fill clearance problem. Keep in Mind the PXI crate connectors (2-3") will stick out and are very vulnerable. maybe mount the PXI crate off to the side?